Practical Field Information about Telecommunication Technologies

Case Studies of Using the Gigabitcompatible Protocol Checker as a Troubleshooting Tool for Home IP Systems

Abstract

This article introduces case studies of using the gigabit-compatible protocol checker as a troubleshooting tool for home Internet protocol (IP) systems. It is the thirteenth in a bimonthly series on the theme of practical field information about telecommunication technologies. This month's contribution is from the Network Interface Engineering Group, Technical Assistance and Support Center, Maintenance and Service Operations Department, Network Business Headquarters, NTT EAST.

1. Introduction

Customer needs are changing as access lines become faster and a wide range of application services come to be provided. There is demand for highquality Internet protocol (IP) services with even higher levels of reliability than in the past. However, the range of configuration patterns for IP equipment within customers' residences has been growing. As a result, the Technical Assistance and Support Center has been receiving many inquiries concerning faults having low reproducibility, such as ones that occur once a day or once a week, as well as enquiries about unusual faults for which a solution cannot be found without analyzing the packets flowing in the customer's home network.

This article presents case studies of using the gigabit-compatible protocol checker, which can easily capture the packet data needed for fault analysis.

2. Overview of gigabit-compatible protocol checker

The gigabit-compatible protocol checker (**Fig. 1**) [1] has two local area network (LAN) ports for mirroring and one LAN port for management. It can be installed within the Ethernet segment in a residence



Fig. 1. External view of gigabit-compatible protocol checker.

as a packet-capture tool that obtains packet data and stores it in a built-in memory. Although it is compact, it provides long-term file acquisition and storage so it is effective for low-reproducibility faults because it can capture data when the fault reappears; the captured data can be analyzed using a LAN analyzer such as Wireshark. Its main functions are: support for packet capture at about 200 Mbit/s over gigabit Ethernet, an operation panel for starting and stopping packet capture without the need to attach a personal computer (PC), and support for remote control from a maintenance center and automatic transfer of data.




Fig. 2. Customer's home configuration and measurement system.

3. Case studies

3.1 Incoming calls disabled on 050 IP phone service

3.1.1 Description of fault

A customer using NTT EAST's B FLET'S service and an ISP's 050 IP phone service upgraded the VoIPgateway from model A to model B, but then found that incoming calls were disabled even though outgoing calls could be made as usual (VoIP: voice over IP). At the time of the fault, the party making the call simply heard a busy signal although the receiving party (the NTT customer) was not using the line. Even when the new model-B gateway equipment was replaced, the problem persisted.

3.1.2 Inspection method

To troubleshoot this problem, we duplicated the customer's system configuration in the office of a field maintenance group and conducted a test to inspect calls made from the Technical Assistance and Support Center to that office. In this test, we inserted the gigabit-compatible protocol checker between the optical network unit (ONU) and the VoIP gateway in the customer's premises to analyze call conditions at the time of the fault (incoming calls not OK) and we investigated any differences in the session initiation protocol (SIP) sequence for two cases: (1) when the VoIP gateway was model A and (2) when it was model B. The test setup is shown in **Fig. 2**.

3.1.3 Inspection results

We found that calls could be received normally when the VoIP gateway was model A (**Fig. 3**). However, when it was model B, after returning a 100Try-




Fig. 3. Incoming-calls OK sequence.




Fig. 4. Incoming-calls not OK sequence.

ing message in response to an INVITE message from the receive-side SIP server, the gateway returned an

2011/2/3	22:34:31 PPPoE	セッション解放[接続先1]
2011/2/3	21:55:34 PPPoE	セッション解放[接続先1]
2011/2/3	20:51:11 PPPoE	セッション解放[接続先1]
2011/2/3	20:29:48 PPPoE	セッション解放[接続先1]
2011/2/3	20:15:25 PPPoE	セッション解放[接続先1]
2011/2/3	19:49:26 PPPoE	セッション解放[接続先1]
2011/2/3	18:51:32 PPPoE	セッション解放[接続先1]

Fig. 5. Router log.




Fig. 6. Customer's home configuration and measurement system.

error "404 Not Found" (**Fig. 4**). This error is returned whenever the called party cannot be detected, which means that the model-B VoIP gateway had judged that the terminal targeted by the incoming call did not exist.

3.1.4 Cause of fault

The results of this inspection led us to consider that although the model-B VoIP gateway received the dial-in number contained in the INVITE message, it could not recognize the terminal targeted by it and returned "404 Not Found". When the model-B VoIP gateway was designed, no assumptions were made about the provider of the 050 IP telephone services; consequently, the maintenance manual did not describe how to set the additional dial-in numbers for a particular provider. This lack of settings caused this problem.

3.1.5 Countermeasure and results

We solved this problem by creating settings for additional dial-in numbers in the model-B VoIP gateway. We also concluded that no problems occurred with incoming calls in the model-A VoIP gateway because it does not refer to settings of additional dialin numbers in the INVITE message of the ISP's 050 IP phone service.

3.2 Occasionally slow Internet access **3.2.1** Description of fault

A customer using a FLET'S optical line reported

that Internet access slowed down sometimes. Upon checking the customer's router log, we found frequent occurrences of the message "PPPo E^{*1} session released" (Fig. 5). Even when the router and ONU were replaced and the accommodation line was changed, the problem remained.

3.2.2 Inspection method

We inserted the gigabit-compatible protocol checker between the ONU and router installed in the customer's residence and proceeded to capture and analyze packets. The system configuration at that time is shown in **Fig. 6**.

3.2.3 Inspection results

Upon analyzing the router log and data captured at the time of this phenomenon, we found that the reception of a PPP (point-to-point protocol) Termination Request from the network side was followed by a PPPoE Active Discovery Termination (PADT) request. Furthermore, upon checking the packet data captured at times other than when this phenomenon occurred, we found that in all cases the reception of a PPP Termination Request was preceded by an idle state with the Internet service provider (ISP) lasting about 10 minutes (**Fig. 7**).

^{*1} PPPoE: Point-to-point protocol (PPP) over Ethernet; a protocol specifically for establishing, setting, and terminating a PPP session between an access concentrator and a terminal device on an Ethernet network.

Tine Some	Destination	Length		Info	
22:24:35.391.	65		TLSVI	Appincation Data	
22:24:35.566	312		TCP	https > m3ua [ACK] Seq=4600 Ack=1717 v	
22:24:35.576	12		TLSV1	Application Data	
22:24:35.571 22:24:45.83			тср	m3ua > https [RST, ACK] Seg=1717 Ack=5	-
			PPP LCP	Echo Request	
22:24:45.83 22:24:47.46			PPP LCP	Echo Reply	
22:24:47.46			PPP LCP	Echo Request	
22:24:47.40			PPP LCP	Echo Reply Echo Request	
22:24:52.42			PPP LCP	Echo Reply	
22:24:32.42			PPP LCP	Echo Request	
22:25:28.20			PPP LCP	Echo Reply 10 min of idle time	
22:25:26.20			PPP LCP	Echo Request	
22:25:45.84			PPP LCP	Echo Reply	
22:25:45.64			PPP LCP	Echo Reguest	
22:25:47.47			PPP LCP	Echo Reply	
22.23.47.47	· ·	, 00			
			: (On	nitted)	
22:34:05.39	a	1 60	PPP LCP	Echo Request	
- 22:34:05-39			RPR LCR	Echo Beply	
22:34:37.03	a .	1 60	PPP LCP	Termination Request	+
22:34:37.12	1. 1	: 60	PPP LCP	Termination Ack	Session terminated
22:34:37.13	a .	1 60	PPPOED	Active Discovery Terminate (PADT)	e e e e e e e e e e e e e e e e e e e
22:34:37.13	1 6		PPPOED	Active Discovery Terminate (PADT)	
22:34:42.18	- E - F	t 60	PPPOED	Active Discovery Initiation (PADI)	
22:34:42.18	a	1 80	PPPOED	Active Discovery Offer (PADO) AC-Name-	
22:34:42.18	1. 1	: 80	PPPOED	Active Discovery Request (PADR) AC-Nar	
22:34:42.18	a .	1 80	PPPOED	Active Discovery Session-confirmation	
22:34:42.70			PPP LCP	Configuration Request	About 6 s
22:34:42.70			PPP LCP	Configuration Request	
22:34:42.70			PPP LCP	Configuration Ack	
22:34:42.70	1. 1		PPP LCP	Configuration Ark	Session reestablished
22:34:42.70	a .		PPP CHAP	Challenge (NAME	Session reestablished
22:34:42.70			PPP CHAP	Response (NAME=	
22:34:42.78			PPP CHAP	Success (MESSAGE='')	
22:34:42.78			PPP IPCP	Configuration Request	
22:34:42.79			PPP IPCP	Configuration Request	
22:34:42.79			PPP IPCP	Configuration Ack	
22:34:42.80			PPP IPCP	configuration Nak	
22:34:42.80			PPP IPCP	Configuration Request	
22:34:42.80		1 60	PPP IPCP	configuration_ack	

Fig. 7. Captured data.

3.2.4 Cause of fault

The PPPoE session was terminated when the idle state with the ISP lasted longer than 10 minutes, and it took about 6 seconds for the session to be reestablished. Therefore, we concluded that the customer would have experienced a slow response when attempting to access the Internet during this 6-s period.

3.2.5 Coping

When we contacted the customer's ISP, we were advised that a PPP session is terminated if the idle time exceeds 10 minutes to prevent unnecessary distribution of global IP addresses. We therefore told the customer that the problem was not caused by NTT equipment and we asked the customer to consult with the ISP.

3.3 Failure of LAN communications between fax and PC

3.3.1 Description of fault

A customer with a home fax machine receives images via a FLET'S optical line and uses a function for automatically transferring those images from the fax to a PC via a LAN. The customer reported that this transfer occasionally failed. Replacing devices within the customer's home did not solve the problem.

3.3.2 Inspection method

To examine the image-data transmission conditions between the fax and PC, we inserted a gigabit-compatible protocol checker between the fax and switch in the customer's home and analyzed the captured data. The system configuration at that time is shown in **Fig. 8**.

3.3.3 Inspection results

Upon analyzing the captured data, we found that communications between the fax and PC were conducted in the form of a TCP (transmission control protocol) session. During normal operation, the session was established on the basis of a TCP 3-way handshake^{*2} (**Fig. 9**) and communications proceeded without any problems. However, when the fault occurred, no Syn/Ack packets were returned from the PC in response to a Syn packet sent from the fax. As a consequence, no session was established and normal communications were not performed. Data captured during normal operations is shown in **Fig. 10** and data captured when the fault occurred is shown in **Fig. 11**.

3.3.4 Cause of fault

Upon inspecting the customer's PC, we found that the firewall settings of the security software installed on it had been modified from their standard values: the settings closed the TCP port, which disrupted communications.

3.3.5 Countermeasure and results

The firewall settings modified by the customer

^{*2 3-}way handshake: A procedure for establishing a connection in TCP. The name derives from the fact that packets are passed three times, as shown in Fig. 9.




Fig. 8. Customer's home configuration and measurement system.




Fig. 9. TCP 3-way handshake.

Time	Source	Destination	Size	Protocol	Info				
10:04:11	.421 192.168.24.A	192.168.24.B	60	TCP	2803	> 2	2869	[SYN]	Seq=0 Win=4380 Len=0 MSS=1460
10:04:11	.421 192.168.24.B	192.168.24.A	60	TCP	2869	> 2	2803	[SYN,	ACK] Seq=0 Ack=1 Win=65535 Len=0 MSS=1460
10:04:11	.422 192.168.24.A	192.168.24.B	60	TCP	2803	> 2	2869	[ACK]	Seq=1 Ack=1 Win=4380 Len=0
10:04:11	.424 192.168.24.A	192.168.24.B	284	TCP	2803	> 2	2869	IPSH,	ACK] Seq=1 Ack=1 Win=4380 Len=230
10:04:11	.424 192.168.24.B	192.168.24.A	261	TCP	2869	> 2	2803	[PSH,	ACKj Sed=1 Ack- PSH, ACKJ Sed=2 Sed=231 Ack-208 handshake is successfully performed.
10:04:11	.424 192.168.24.B	192.168.24.A	1259	TCP	2869	> 2	2803	[FIN,	PSH, ACK] Seq=2
10:04:11	.426 192.168.24.A	192.168.24.B	60	TCP	2803	> 2	2869	[ACK]	Seq=231 Ack=208 nandsnake is successfully performed.
10:04:11	.436 192.168.24.A	192.168.24.B	60	TCP	2803	> 2	2869	[ACK]	Seq=231 Ack=1414 Win=3175 Len=0
10:04:11	.438 192.168.24.A	192.168.24.B	60	TCP	2803	> 2	2869	[FIN,	ACK] Seq=231 Ack=1414 Win=4380 Len=0
10:04:11	.438 192.168.24.B	192.168.24.A	60	TCP	2869	> 2	2803	[ACK]	Seg=1414 Ack=232 Win=65305 Len=0

*IP addresses are partially shown. 192.168.24.A: FAX, 192.168.24.B: PC

Fig. 10. Fax LAN port communications during normal operations.

Time	Source	Destination	Size	Protocol	Info	
10:09:05.038	192.168.24.A	192.168.24.B	60		2804 > 2869 [SYN] Seq=0 Win=4380 Len=0 MSS=1460	
10:09:05.496	192.168.24.A	192.168.24.B	60	TCP	2804 > 2869 SYN Seq=0 Win=4380 Len=0 MSS=1460	Fax sends a Syn
10:09:07.076	192.168.24.A	192.168.24.B	60	TCP	2805 > 2869 [SYN] Seq=0 Win=4380 Len=0 MSS=1460	packet to the PC
10:09:07.546	192.168.24.A	192.168.24.B	60	TCP	2805 > 2869 [SYN] Seq=0 Win=4380 Len=0 MSS=1460	but receives no
10:09:14.274	192.168.24.A	192.168.24.B	60	TCP	2806 > 2869 [SYN] Seq=0 Win=4380 Len=0 MSS=1460	
10:09:14.719	192.168.24.A	192.168.24.B	60	TCP	2806 > 2869 [SYN] Seq=0 Win=4380 Len=0 MSS=1460	response.
10:14:17.297	192.168.24.A	192.168.24.B	60	TCP	2807 > 2869 [SYN] Seq=0 Win=4380 Len=0 MSS=1460	
10:14:17.736	192.168.24.A	192.168.24.B	60	TCP	2807 > 2869 [SYN] Seq=0 Win=4380 Len=0 MSS=1460	

*IP addresses are partially shown. 192.168.24.A: FAX, 192.168.24.B: PC

Fig. 11. Fax LAN port communications at time of fault occurrence.

were restored to their standard values. This action eliminated the fault.

4. Concluding remarks

This article presented case studies of using a gigabit-compatible protocol checker to troubleshoot faults. Packet analysis is becoming an essential tool for investigating IP-related faults, and it is hoped that

the reader has found the case studies described here to be informative and useful.

References

- "Gigabit-compatible Protocol Checker," NTT Technical Review, Vol. 10, No. 7, 2012. https://www.ntt-review.jp/archive/ntttechnical.php?contents=ntr2012 07fa3.html
- [2] FLET'S services. http://flets.com/english/